

# THSSD Software User Manual

## Table of contents

---

Getting started .....	3
System requirements.....	3
USB communications .....	3
Software overview.....	4
Chart.....	5
Actual Force and Position.....	9
Max. Force and Position.....	10
Manage Curves .....	10
Status bar .....	11
About window .....	11
Main menu.....	12
Machine.....	12
Method.....	14
Report .....	14
Diagnose .....	14
Language .....	15
Testing methods .....	16
Tensile test.....	16
E-modulus calculation .....	18
Compression test .....	19
Hysteresis.....	20
Force regulation .....	22
Friction test .....	24
Software special functions .....	26
Software modes.....	26
Automatic reconnect .....	26

## Getting Started

---

### System requirements

**Hardware Requirements:**

1. USB 2.0 communication port.
2. CPU: Dual Core 1.6 GHz or higher
3. RAM: 2 GB or higher
4. 1024x768 screen resolution or higher
5. Mouse or touch-pad (notebooks)
6. Keyboard

**Software Requirements:**

Operating system: Win XP (32-bit version only), Vista, Win 7, Win 8, Win 10

### USB Communications


**Hardware requirements:**

1. Before you use this software you need to install FTDI drivers for Tensile Tester.  
You can find driver in programs folder or download from FTDI chip site:

<http://www.ftdichip.com/Drivers/D2XX.htm>


2. Unpack files from distribution archive. (you can use [7-zip](#) or [winrar](#) to manipulate archives)
3. Run .exe file

## Software Overview




1. Main Menu
2. Sub-menu items
3. Chart
4. Actual force and position
5. Maximum force and position
6. Chart control panel

## Chart




X coordinate - Way in mm  
 Y coordinate - Force in Newton


**Note:** X and Y units can be changed




User can also rename axis




Result:





User can zoom specific area by making rectangular selection.  
 Press & hold mouse right button and move cursor to navigate through chart.  
 To zoom out make rectangular selection from right to left.  
 Coordinate values will change according to zoom level.





Hovering mouse over curves will display Way and Force at specific points





Scale chart via pop-up menu



setting line thickness via pop-up menu.  
valid range: 0...9 pixel



snapshot via pop-up menu



## Actual Force and Position

27-3-2017 10:13:15

Force:

**4.3 N**

Position:

**0.00 mm**

Statistics
Max. Load
<b>0</b>
at
<b>0</b>

User can select precision of current force display.  
User should make right click and from pop-up menu choose the resolution.

Force:	<b>-32.8 N</b>
Position:	<b>0.00 mm</b>
Statistics	

- 0.0
- 0.00
- 0.000
- 0.0000

On the right panel actual Force and Position is shown.  
Their values change dynamically when the test runs.  
To reset their values double click each of them or reset both values from main menu (>0<)

## Max. Force and Position

Force:

**-32.8 N**

Position:

**0.00 mm**

Statistics

Max. Force

**0**

at

**0**

After the test is completed, Max. Force and Position is displayed on the right hand side. If multiple curves are shown, select/hide them as shown on the picture above.

select position source:

Position:

**0.00 mm**

Encoder

Extensometer

Statistic

Max. Force

## Manage Curves

 Project(1)

User can manage multiple curves from this area. Previous test results can be imported or actual test results exported. Individual curves can be hidden/deleted/exported etc...

## Status Bar

Status: OFFLINE    Points: 463    Cycle No: None        Time [s]: 9.25    Speed: 19.9

**Status** - shows current status of software. See [software modes](#);

**Points count** - show count of data points in latest test curve;

**COM port** - shows current communication port;


**Cycle No-** shows cycle number;

**Progress bar** - shows progress of current test;

**Time [s]:** - time interval from start of test;

**Speed [mm/min]:** - speed of test;


## About window



### About window shows:


- Name of software
- Version of software
- Firmware version (only in ONLINE mode)
- Nominal load of load cell (only in ONLINE mode)
- Measuring units (English/Metric)

## Main Menu



From Main Menu user has options to start/stop tests, select testing methods, export reports and diagnose machine.

## Machine




**Start** - Start the test

**Stop** - Stop the test


**>0<** - Reset load cell and position (set both to 0)

**Return** - Return crosshead to starting position




**Up** - Move crosshead up

**Down** - Move crosshead down



1. Save user settings in \*.ini file

2. Restore user settings from \*.ini file



**Options** - Setting user options (automatic crosshead return, curve saving modes, autosave default folder, etc...)

**Options** ✕

**Return to start position**

Automatic return Vo [mm/min]

Fast return (400 mm/min)

**Saving mode**

\*.set files. Multiple curves in one file (example.set)

\*.bin files. Single curve in one file (example.bin)

\*.setx files. Multiple curves in one file (recommended)

**User Settings**

Show input window before start  Open XLSX export file

Lock testing settings  Open XLSX report file

Show Chat FPS  Show Legend

**Autosave**

Automatic saving

Folder:

Auto Export Stats to XLSX  Auto open Stats XLSX File

**Units**


Metric  English

## Method



From this section user can select testing method.

## Report



From this section user can generate and export reports.

**Print Chart** - Prints actual chart


**\*.xlsx Report** – generates report based on \*.xlsx template

**\*.docx Report** – generates report based on \*.docx template

**Report** - generates standard based on internal template system. Possible to export in \*.pdf file format



**Export to Excel** - Exports report to excel file

**Export to Text** - Exports report to text file




**User Logo** - User can select company logo or custom image (used in standard **Report**)

## Diagnose




HW diagnostic section shows current state of machine. If an error occurs during the test - motor error, limit switches, etc, corresponding indicators will be highlighted. on the right panel user can reset machine, apply/remove compensation and start stiffness compensation tool.

## Language



To change language, click on question mark icon on right hand side and choose your language from menu.




## Testing Methods

There are 7 different testing methods implemented in software:

- Tensile test
- Compression test
- Hysteresis
- Force regulation
- Friction test
- Peeling test
- 3-point Bending test

User can select testing methods from main menu under the ['Method'](#) tab.

When user selects method, method settings and parameters will be shown next to the 'Chart' tab:



## Tensile test

**Parameter description:**

**Machine Settings:**

- Speed [mm/min] - Machine speed during the test.
- Displacement [mm] - Maximal travel distance. When maximal distance is reached, test is stopped.
- Maximal Load FI [N] - Maximal load during test. When maximal load is reached, test is stopped.
- Preload [N] - Software starts chart plotting, when this value is reached. Default value is 0.
- Breaking Force (dF) [N] - Allowed force to be dropped during the test. if force dropping is more than given value, machine detects braking and test is finished.

**Note:** Before starting the test, user should click on 'Update' to send given values to machine.

**Chart Settings:**

User can set left and bottom axis units.

**Elastic modulus:**

Set scan limits in [%]


Select Extensometer data for usage in E-modulus calculation.

Click on 'Set scan limits'

These limits will be used for multiple E-modulus calculation.

**Project Settings:**



Additional project information.



In 'Sample description' tab, user will enter sample data: width, thickness, length, cross-section, material, shape, etc...

## E-modulus Calculation

Right click on curve name -> 'Elastic / Flexural modulus' .



## Compression Test

### Parameter description:

#### Machine Settings:

- Speed [mm/min] - Machine speed during the test.
- Displacement [mm] - Maximal travel distance. When maximal distance is reached, test is stopped.
- Maximal Load [N] - Maximal load during test. When maximal load is reached, test is stopped.
- Preload [N] - Software starts chart plotting, when this value is reached. Default value is 0.
- Breaking Force [N] - Allowed force to be dropped during the test. if force dropping is more than given value, machine detects braking and test is finished.

**Note:** Before starting the test, user should click on 'Update' to send given values to machine.

#### Chart Settings:

User can set left and bottom axis units.

#### Project Settings:

Additional project information.

The screenshot shows the 'Compression Test' configuration window. It has a 'Chart' tab selected at the top. Below the tab are two sub-tabs: 'Settings' and 'Sample Description'. The 'Settings' sub-tab is active, showing three columns of controls:

- Machine:**
  - Speed [mm/min]: 100
  - Displacement [mm]: 15.225
  - Maximal Load [N]: 100
  - Preload [N]: 0.25
  - Breaking Force [N]: 10
  - Buttons: Read Breaking Force, Update
- Chart:**
  - Y-axis:  invert, dropdown: Load [N]
  - X-axis:  invert, dropdown: Displacement [mm]
- Project:**
  - Part Number: [ ]
  - Order No: [ ]
  - Method: [ ]
  - Tester: [ ]
  - Customer: [ ]
  - Remark: [ ]

In 'Sample description' tab, user will enter sample data: width, thickness, length, cross-section, material, shape, etc...

## Hysteresis

Chart Hysteresis Test

Settings Sample Description

**Machine**

Speed [mm/min]

Displacement [mm]

Maximal Load [N]

Preload [N]

Fhys [N]

Cycles count

Holding Time [sec]

**Chart**

Y-axis:  
 invert

X-axis:  
 invert

**Options**  
 Compression

**Project**

Part Number:

Order No:

Method:

Tester:

Customer:

### Parameter description:

#### Machine Settings:

- Speed [mm/min] - Machine speed during the test.
- Displacement [mm] - Maximal travel distance. When maximal distance is reached, test is stopped.
- Maximal Load [N] - Maximal force during test. When maximal force is reached, test is stopped.
- Preloading [N] - Software starts chart plotting, when this value is reached. Default value is 0.
- Fhys [N] - hystesis mode limited by given force. Fhys should be less then Max. Load [N].
- Cycles count - Number of test iterations.
- Holding Time [sec] - Time interval machine holds, when max. distance is reached.


**Note:** Before starting the test, user should click on 'Update' to send given values to machine.

#### Chart Settings:

User can set left and bottom axis units.

#### Project Settings:

Additional project information.



In 'Sample description' tab, user will enter sample data: width, thickness, length, cross-section, material, shape, etc...

## Force Regulation

Chart **Constant force**

Settings **Sample Description**

**Machine**

Load [N]

Displacement [mm]

Holding Time [Sec]  
(max 604800)

Compression

Soft      Hardness: 5

1 2 3 4 5 6 7 8 9 10

**Chart**

Y-axis:  
 invert

X-axis:  
 invert

**Project**

Part Number:

Order No:

Method:

Tester:

Customer:

### Parameter Description:

#### Machine Settings:

- Load [N] - When regulation force is reached, machine keeps force for specified time interval.
- Displacement [mm] - Maximal distance machine will travel.
- Holding Time [sec] - Time interval machine holds, when regulated force is reached.

**Note:** Before starting the test, user should click on 'Update' to send given values to machine.

#### Chart Settings:

User can set left and bottom axis units.


#### Project Settings:

Additional project information.

In 'Sample description' tab, user will enter sample data: width, thickness, length, cross-section, material, shape, etc...

Dimensions

Parameter	Value
L0, mm	100
W, mm	50
T, mm	3
Material	Plastic
Area	150



A 3D perspective diagram of a rectangular block. The front face is shaded with a cross-hatch pattern. Three dimensions are indicated with red arrows: L0 (length) along the bottom edge, W (width) along the left edge, and T (thickness) along the vertical edge. A mouse cursor is positioned over the bottom-left corner of the front face.

## Friction Test

Settings

Sample description

**Machine**

Speed [mm/min]

Displacement [mm]

Maximal Load [N]

Preload [N]

Breaking Force [N]

**Chart**

Y-axis:

X-axis:

**Project**

Part Number:

Order No:

Method:

Tester:

Customer:

### Parameter description:

#### Machine Settings:

- Speed [mm/min] - Machine speed during the test.
- Displacement [mm] - Maximal travel distance. When maximal distance is reached, test is stopped.
- Maximal Load FI [N] - Maximal load during test. When maximal load is reached, test is stopped.
- Preload [N] - Software starts chart plotting, when this value is reached. Default value is 0.
- Breaking Force [N] - Allowed force to be dropped during the test. if force dropping is more than given value, machine stops and test is finished.

**Note:** Before starting the test, user should click on 'Update' to send given values to machine.

#### Chart Settings:

User can set left and bottom axis units.

#### Project Settings:


Additional project information.

Test scheme

F0 - Nominal load

L0 - Length [mm]


Width [mm]



Calculate Nominal Load

Sled Weight  g

Calculation Settings



X1, [mm] - starting offset of scanning area

X2, [mm] - scan length

Calculation results:

In 'Sample description' tab, user will enter sample data: Nominal load, length, width, sledge weight, etc...

## Software special functions

---

### Software modes

In software exist 3 modes:

- **OFFLINE mode**- in this mode you can work without machine. Also this mode automatically activates, when software suddenly loses connection with machine.
- **ONLINE mode**- this mode is used for setting up machine and preparing for test.
- **RUNNING mode**- this mode automatically activates when machine starts test.

#### **OFFLINE mode**

We use this mode, when software loses connection with machine, or you want use program without machine (for example: user wants analyze test results in different office, where ZPM machines not present).

In this mode you can load saved curves, make reports etc.

#### **ONLINE mode**

In this mode, software is connected with machine and ready to transmit data to machine and receive data back from the machine.

You can control machine, prepare for test etc...

#### **RUNNING mode**

In this mode software is connected with machine and receives test data from machine.

In this mode machine controls buttons locked, except "Stop" button.

Chart control tool is locked too.

### Automatic reconnect

When connection with machine is lost, software automatically tries to reconnect. If within 10 attempts communication is not restored, software automatically switches to OFFLINE mode.

Revision history:

26.03.2019 – D.