

FAQ: How to switch power supply voltage to 110V?

Tooling: You need flat screwdriver.



1. Look at backside of your machine. Here is Power Switch. It looks like this:




Voltage marks indicates what voltage is selected. Now is 220-240V.

2. With screwdriver open fuse box:



3. Now rotate it like it shown on picture below:



4. Now insert fuse box into switch. Also be attentive with voltage mark.



Now is selected to 110V. See Picture below. All done.

